

PYROMETRIC COMPANY

1312 South 96TH Street Seattle, Washington 98108

Service Technician: Mile Dun Sa

(206) 762-8307 www.pyrometric.com Fax (206) 763-9459

Form 1 03/31/00

CALIBRATION REPORT

Customer:	WASHINGTON STA	TE PATROL	P.O.# 00081650	Test No	Test No. 19577	
Location:	PROPERTY MANAG	GEMENT CONTROL	Attn: GREG PARRIOT	T Test Date	e: 11/09/04	
Instrument:	TOLEDO LOAD CEI	LL C2P1-50K/RICE LAKE	INDICATOR IQ PLUS 3	10 Recall Date	e: 11/09/06	
Serial No.				Req'd Accy: ± 1% Indicated		
As Found Condition: In Tol			Out of Tol.	Repair	_	
STANDARD 0.0 LBF.		INSTR	RUMENT	CORRECTION		
			0 LBF.		0.0 LBF.	
2502.8		2:	2500		2.8	
5000.0		50	5000		0.0	
7499.2		7:	7500		-0.8	
9997.7		10	10000		-2.3	
12498.6		12:	12500		-1.4	
14997.4		150	15000		-2.6	
17497.7		179	17500		-2.3	
19996.6		20	20000		-3.4	
22495.8		22	500	-4.2		
24995.5		25	25000		-4.5	
I Certify, Under Penalty of Perjury, Under the Laws Governing the State of Washington that the foregoing is True and Correct.						
Condition at time of testing: Temperature: 68°F Relative Humidity: 46 %						
Remarks: The	above equipment meets or ex	xceeds the requirements of the fol	lowing specifications:			
PER. CUST	OMER,	1	,,	,		
Test procedure used: 4.3.2 Our calibration system complies with ANSI/NCSL Z540-1. All test equipment used is traceable to standards of the National Institute of Standards and Technology.						
Test Equipment		Serial No.	Test Date	Recall Date	Test No.	
REVERE LOAD CELL 70		707481	04/15/04	04/15/05	17555	
INTERFACE LOAD CELL		117123A	04/16/04	04/16/05	17555	